



OSCAR

*Classic*

III



Os 1740  
crp. 6

Os 1745  
crp. 6

Os 1747  
crp. 6

Os 1750  
crp. 6

Os 1755  
crp. 7

Os 1757  
crp. 7

Os 1760  
crp. 7

Os 1765  
crp. 7

Os 1767  
crp. 8

Os 1770  
crp. 8

Os 1775  
crp. 8

Os 1777  
crp. 8

Os 1780  
crp. 9

Os 1785  
crp. 9

Os 1787  
crp. 9

Os 1790  
crp. 9

Os 1795  
crp. 10

Os 1797  
crp. 10

Os 1805  
crp. 10

Os 1807  
crp. 10

Os 1810  
crp. 11

Os 1815  
crp. 11

Os 1817  
crp. 11

Os 1820  
crp. 11

Os 1825  
crp. 12

Os 1827  
crp. 12

Os 1830  
crp. 12

Os 1835  
crp. 12

Os 1837  
crp. 13

Os 1840  
crp. 13

Os 1845  
crp. 13

Os 1847  
crp. 13

Os 1855  
crp. 14

Os 1857  
crp. 14

Os 1860  
crp. 14

Os 1865  
crp. 14

Os 1867  
crp. 15

Os 1870  
crp. 15

Os 1875  
crp. 15

Os 1877  
crp. 15

Os 1880  
crp. 16

Os 1885  
crp. 16

Os 1887  
crp. 16

Os 2143  
crp. 17

Os 2144  
crp. 17

Os 2145  
crp. 17

Os 2146  
crp. 17

Os 2147  
crp. 18

Os 2148  
crp. 18

Os 2149  
crp. 18

Os 2150  
crp. 18

Os 2151  
crp. 19

Os 2152  
crp. 19

Os 2153  
crp. 19

Os 2154  
crp. 19

Os 2155  
crp. 20

Os 2156  
crp. 20

Os 2157  
crp. 20

Os 2158  
crp. 20

Os 2159  
crp. 21

Os 2160  
crp. 21

Os 2161  
crp. 21

Os 2162  
crp. 21

Os 2163  
crp. 22

Os 2164  
crp. 22

Os 2165  
crp. 22

Os 2166  
crp. 22

Os 2167  
crp. 23

Os 2168  
crp. 23

Os 2169  
crp. 23

Os 2170  
crp. 23

Os 2171  
crp. 24

Os 2172  
crp. 24

Os 2173  
crp. 24

Os 2174  
crp. 24

Os 2175  
crp. 25

Os 2176  
crp. 25

Os 2177  
crp. 25

Os 2178  
crp. 25

Os 2179  
crp. 26

Os 2180  
crp. 26

Os 2181  
crp. 26

Os 2182  
crp. 26

Os 2183  
crp. 27

Os 2184  
crp. 27

Os 2185  
crp. 27

Os 2186  
crp. 27

Os 2187  
crp. 28

Os 2188  
crp. 28

Os 2189  
crp. 28

Os 2190  
crp. 28

Os 2191  
crp. 29

Os 2192  
crp. 29

Os 2193  
crp. 29

Os 2194  
crp. 29

Os 2195  
crp. 30

Os 2196  
crp. 30

Os 2197  
crp. 30

Os 2198  
crp. 30

Os 2199  
crp. 31

Os 2200  
crp. 31

Os 2201  
crp. 31

Os 2202  
crp. 31

Os 2559  
crp. 32

Os 2560  
crp. 32

Os 2561  
crp. 32

Os 2562  
crp. 32

Os 2563  
crp. 33

Os 2564  
crp. 33

Os 2565  
crp. 33

Os 2566  
crp. 33

Os 2567  
crp. 34

Os 2568  
crp. 34

Os 2569  
crp. 34

Os 2570  
crp. 34

Os 2571  
crp. 35

Os 2572  
crp. 35

Os 2573  
crp. 35

Os 2574  
crp. 35

Os 2575  
crp. 36

Os 2576  
crp. 36



Os 2577 r.p. 36 Os 2578 r.p. 36 Os 2579 r.p. 37 Os 2580 r.p. 37 Os 2581 r.p. 37 Os 2582 r.p. 37 Os 2583 r.p. 38 Os 2584 r.p. 38 Os 2585 r.p. 38

Os 2586 r.p. 38 Os 2587 r.p. 39 Os 2588 r.p. 39 Os 2589 r.p. 39 Os 2590 r.p. 39 Os 2591 r.p. 40 Os 2592 r.p. 40 Os 2593 r.p. 40 Os 2594 r.p. 40

Os 2595 r.p. 41 Os 2596 r.p. 41 Os 2597 r.p. 41 Os 2598 r.p. 41 Os 2599 r.p. 42 Os 2600 r.p. 42 Os 2601 r.p. 42 Os 2602 r.p. 42 Os 2603 r.p. 43

Os 2604 r.p. 43 Os 2605 r.p. 43 Os 2606 r.p. 43 Os 2607 r.p. 44 Os 2608 r.p. 44 Os 2609 r.p. 44 Os 2610 r.p. 44 Os 2611 r.p. 45 Os 2612 r.p. 45

Os 2613 r.p. 45 Os 2614 r.p. 45 Os 2615 r.p. 46 Os 2616 r.p. 46 Os 2617 r.p. 46 Os 2618 r.p. 46 Os 2619 r.p. 47 Os 2620 r.p. 47 Os 2621 r.p. 47

Os 2622 r.p. 47 Os 2623 r.p. 48 Os 2624 r.p. 48 Os 2625 r.p. 48 Os 2626 r.p. 48 Os 2627 r.p. 49 Os 2628 r.p. 49 Os 2629 r.p. 49 Os 2630 r.p. 49

Os 2631 r.p. 50 Os 2632 r.p. 50 Os 2633 r.p. 50 Os 2634 r.p. 50 Os 2635 r.p. 51 Os 2636 r.p. 51 Os 2637 r.p. 51 Os 2638 r.p. 51 Os 2639 r.p. 52

Os 2640 r.p. 52 Os 2641 r.p. 52 Os 2642 r.p. 52 Os 2643 r.p. 53 Os 2644 r.p. 53 Os 2645 r.p. 53 Os 2646 r.p. 53 Os 2647 r.p. 54 Os 2648 r.p. 54

Os 2649 r.p. 54 Os 2650 r.p. 54 Os 2651 r.p. 55 Os 2652 r.p. 55 Os 2653 r.p. 55 Os 2654 r.p. 55 Os 2655 r.p. 56 Os 2656 r.p. 56 Os 2657 r.p. 56

Os 2658 r.p. 56 Os 2659 r.p. 57 Os 2660 r.p. 57 Os 2661 r.p. 57 Os 2662 r.p. 57 Os 2663 r.p. 58 Os 2664 r.p. 58 Os 2665 r.p. 58 Os 2666 r.p. 58

Os 2667 r.p. 59 Os 2668 r.p. 59 Os 2669 r.p. 59 Os 2670 r.p. 59 Os 2671 r.p. 60 Os 2672 r.p. 60 Os 2673 r.p. 60 Os 2674 r.p. 60 Os 2675 r.p. 61

Os 2676 r.p. 61 Os 2677 r.p. 61 Os 2678 r.p. 61 Os 2679 r.p. 62 Os 2680 r.p. 62 Os 2681 r.p. 62 Os 2682 r.p. 62 Os 2683 r.p. 63 Os 2684 r.p. 63

Os 2685 r.p. 63 Os 2686 r.p. 63 Os 2687 r.p. 64 Os 2688 r.p. 64 Os 2689 r.p. 64 Os 2690 r.p. 64 Os 2691 r.p. 65 Os 2692 r.p. 65 Os 2693 r.p. 65

Os 2694 r.p. 65 Os 2695 r.p. 66 Os 2696 r.p. 66 Os 2697 r.p. 66 Os 2698 r.p. 66 Os 2699 r.p. 67 Os 2700 r.p. 67 Os 2701 r.p. 67 Os 2702 r.p. 67



Os 2703 r.p. 68 Os 2704 r.p. 68 Os 2705 r.p. 68 Os 2706 r.p. 68 Os 2707 r.p. 69 Os 2708 r.p. 69 Os 2709 r.p. 69 Os 2710 r.p. 69 Os 2711 r.p. 70

Os 2712 r.p. 70 Os 2713 r.p. 70 Os 2714 r.p. 70 Os 2715 r.p. 71 Os 2716 r.p. 71 Os 2717 r.p. 71 Os 2718 r.p. 71 Os 2719 r.p. 72 Os 2720 r.p. 72

Os 2721 r.p. 72 Os 2722 r.p. 72 Os 2723 r.p. 73 Os 2724 r.p. 73 Os 2725 r.p. 73 Os 2726 r.p. 73

Os 3056 r.p. 74 Os 3057 r.p. 74 Os 3058 r.p. 74 Os 3059 r.p. 74 Os 3060 r.p. 75 Os 3061 r.p. 75 Os 3062 r.p. 75 Os 3063 r.p. 75 Os 3064 r.p. 76

Os 3065 r.p. 76 Os 3066 r.p. 76 Os 3067 r.p. 76 Os 3068 r.p. 77 Os 3069 r.p. 77 Os 3070 r.p. 77 Os 3071 r.p. 77 Os 3072 r.p. 78 Os 3073 r.p. 78

Os 3074 r.p. 78 Os 3075 r.p. 78 Os 3076 r.p. 79 Os 3077 r.p. 79 Os 3078 r.p. 79 Os 3079 r.p. 79 Os 3080 r.p. 80 Os 3081 r.p. 80 Os 3082 r.p. 80

Os 3083 r.p. 80 Os 3084 r.p. 81 Os 3085 r.p. 81

Os 4041 r.p. 82 Os 4042 r.p. 82 Os 4043 r.p. 82 Os 4044 r.p. 82 Os 4045 r.p. 83 Os 4046 r.p. 83 Os 4047 r.p. 83 Os 4048 r.p. 83 Os 4049 r.p. 84

Os 4050 r.p. 84 Os 4051 r.p. 84 Os 4052 r.p. 84 Os 4053 r.p. 85 Os 4054 r.p. 85 Os 4055 r.p. 85 Os 4056 r.p. 85 Os 4057 r.p. 86 Os 4058 r.p. 86

Os 4059 r.p. 86 Os 4060 r.p. 86 Os 4061 r.p. 87 Os 4062 r.p. 87 Os 4063 r.p. 87 Os 4064 r.p. 87 Os 4065 r.p. 88 Os 4066 r.p. 88 Os 4067 r.p. 88

Os 4068 r.p. 88 Os 4069 r.p. 89 Os 4070 r.p. 89 Os 4071 r.p. 89 Os 4072 r.p. 89 Os 4073 r.p. 90 Os 4074 r.p. 90 Os 4075 r.p. 90 Os 4076 r.p. 90

Os 4077 r.p. 91 Os 4078 r.p. 91 Os 4079 r.p. 91 Os 4080 r.p. 91 Os 4081 r.p. 92 Os 4082 r.p. 92 Os 4083 r.p. 92 Os 4084 r.p. 92 Os 4085 r.p. 93

Os 4086 r.p. 93 Os 4087 r.p. 93 Os 4088 r.p. 93 Os 4089 r.p. 94 Os 5147 r.p. 94 Os 5148 r.p. 94 Os 5149 r.p. 94



Os 7127  
стр. 95



Os 7128  
стр. 95



Os 7129  
стр. 95



Os 7130  
стр. 95



Os 7131  
стр. 96



Os 7132  
стр. 96



Os 7133  
стр. 96



Os 7134  
стр. 96



Os 7135  
стр. 97



Os 7136  
стр. 97



Os 7137  
стр. 97



Os 7138  
стр. 97



Os 7139  
стр. 98



Os 7140  
стр. 98



Os 7141  
стр. 98



Os 7142  
стр. 98



Os 7143  
стр. 99



Os 7144  
стр. 99



Os 7145  
стр. 99



Os 7146  
стр. 99



Os 7147  
стр. 100



Os 7148  
стр. 100



Os 7149  
стр. 100



Os 7150  
стр. 100



Os 7151  
стр. 101



Os 7152  
стр. 101



Os 7153  
стр. 101



Os 7154  
стр. 101



Os 7155  
стр. 102



Os 7156  
стр. 102



Os 7157  
стр. 102



Os 7158  
стр. 102



Os 7159  
стр. 103



Os 7160  
стр. 103



Os 7161  
стр. 103



Os 7162  
стр. 103



Os 7163  
стр. 104



Os 7164  
стр. 104



Os 7165  
стр. 104



Os 7166  
стр. 104



Os 7167  
стр. 105



Os 7168  
стр. 105



Os 7169  
стр. 105



Os 7170  
стр. 105



Os 7171  
стр. 106



Os 7172  
стр. 106



Os 7173  
стр. 106



Os 7174  
стр. 106



Os 7175  
стр. 107



Os 7176  
стр. 107



Os 7177  
стр. 107



Os 7178  
стр. 107



Os 7179  
стр. 108



Os 7180  
стр. 108



Os 7181  
стр. 108



Os 7182  
стр. 108



Os 7183  
стр. 109



Os 7184  
стр. 109



Os 7185  
стр. 109



Os 7186  
стр. 109



Os 7187  
стр. 110



Os 7188  
стр. 110



Os 7189  
стр. 110



Os 7190  
стр. 110



Os 7191  
стр. 111



Os 7192  
стр. 111



Os 7193  
стр. 111



Os 7194  
стр. 111



Os 7195  
стр. 112



Os 7196  
стр. 112



Os 7197  
стр. 112



Os 7198  
стр. 112



Os 7199  
стр. 113



Os 7200  
стр. 113



Os 7201  
стр. 113



Os 7202  
стр. 113



Os 7203  
стр. 114



Os 7204  
стр. 114



Os 7205  
стр. 114



Os 7206  
стр. 114



Os 7207  
стр. 115



Os 7208  
стр. 115



Os 7209  
стр. 115



Os 7210  
стр. 115



Os 7211  
стр. 116



Os 7212  
стр. 116



Os 7213  
стр. 116



Os 7214  
стр. 116



Os 7215  
стр. 117



Os 7216  
стр. 117



Os 7217  
стр. 117



Os 7218  
стр. 117



Os 7219  
стр. 118



Os 7220  
стр. 118



Os 7221  
стр. 118




Os 7222  
стр. 118



Os 7223  
стр. 119



Os 7224  
стр. 119



Os 7225  
стр. 119



Os 7226  
стр. 119



Os 7227  
стр. 120



Os 7228  
стр. 120



Os 7229  
стр. 120

Os 1740

Вес: 4,4

Вставки: Кр 2,3-2; Кр 2,1-2;  
Кр 2,0-2; Кр 1,9-2; Кр 1,8-2; Кр  
1,7-2

Os 1745

Вес: 3,2

Вставки: Кр 1,8-4; Кр 1,7-4; Кр  
1,6-4; Кр 1,5-4; Кр 1,3-4

Os 1747

Вес: 3,4

Вставки: Кр 2,1-2; Кр 2,0-2; Кр  
1,9-2; Кр 1,8-2; Кр 1,7-2; Кр 1,6-  
2; Кр 1,3-2

Os 1750

Вес: 5,4

Вставки: Кр 2,5-1; Кр 2,1-1;  
Кр 2,0-1; Кр 1,8-1; Кр 1,7-1; Кр  
1,6-1



Os 1740



Os 1745



Os 1747



Os 1750





Os 1755



Os 1757



Os 1760



Os 1765



Os 1755

Вес: 2,7

Вставки: Кр 2,3-2; Кр 2,2-2; Кр 2,1-2; Кр 2,0-2; Кр 1,8-2

Os 1757

Вес: 2,3

Вставки: Кр 2,5-1; Кр 2,3-1; Кр 2,2-1; Кр 2,1-1; Кр 2,0-1; Кр 1,8-1

Os 1760

Вес: 4,4

Вставки: Кр 2,5-1; Кр 2,3-1; Кр 2,1-1; Кр 2,0-1; Кр 1,8-2; Кр 1,7-1

Os 1765

Вес: 3,2

Вставки: Кр 2,1-2; Кр 2,0-2; Кр 1,8-2; Кр 1,6-2; Кр 1,5-2; Кр 1,3-2



Os 1767



Os 1767

Вес: 2,7

Вставки: Кр 2,5-1; Кр 2,3-1;  
Кр 2,1-1; Кр 2,0-1; Кр 1,8-2; Кр  
1,7-1



Os 1770



Os 1770

Вес: 5,7

Вставки: Кр 2,5-1; Кр 2,3-1; Кр  
2,2-1; Кр 2,1-1; Кр 2,0-1; Кр  
1,9-1; Кр 1,8-2



Os 1775



Os 1775

Вес: 3,4

Вставки: Кр 2,1-2; Кр 2,0-2; Кр  
1,8-2; Кр 1,7-2; Кр 1,6-2



Os 1777



Os 1777

Вес: 3,4

Вставки: Кр 2,5-1; Кр 2,3-1; Кр  
2,2-1; Кр 2,1-1; Кр 2,0-1; Кр 1,9-  
1; Кр 1,8-2



Os 1780



Os 1785



Os 1780

Вес: 4,4

Вставки: Ов 7,5x5,5-1; Кр 1,3-16

Os 1785

Вес: 4,6

Вставки: Ов 6,5x4,5-2; Кр 1,3-14; Кр 1,2-14



Os 1787



Os 1787

Вес: 2

Вставки: Ов 7,5x5,5-1; Кр 1,3-16



Os 1790



Os 1790

Вес: 5,4

Вставки: Мз 7x4-1; Кр 1,6-11

Os 1795

Вес: 3,8

Вставки: Мз 5х3-2; Кр 1,5-18



Os 1795



Os 1797

Вес: 2,7

Вставки: Мз 7х4-1; Кр 1,6-11



Os 1797



Os 1805

Вес: 2,1

Вставки: Кр 2,5-4; Кр 1,6-8



Os 1805



Os 1807

Вес: 1,6

Вставки: Кр 3,0-3; Кр 1,7-8



Os 1807






Os 1810



Os 1815



Os 1810  
Вес: 6,8  
Вставки: Мз 7x4-1; Кр 1,4-20



Os1817



Os 1815  
Вес: 4,8  
Вставки: Мз 6x3-2; Кр 1,4-20

Os 1817  
Вес: 3,2  
Вставки: Мз 7x4-1; Кр 1,5-14



Os1820



Os 1820  
Вес: 3,4  
Вставки: Мз 7x4-1; Кр 1,5-16

Os 1825  
Вес: 3,2  
Вставки: Мз 5х3-2; Кр 1,4-28



Os 1825



Os 1827  
Вес: 1,4  
Вставки: Мз 7х4-1; Кр 1,5-16



Os 1827



Os 1830  
Вес: 4  
Вставки: Кр 1,4-8; Кр 1,5-2



Os 1830



Os 1835  
Вес: 4  
Вставки: Кр 1,4-6; Кр 1,3-4



Os 1835





Os 1837



Os 1840



Os 1845



Os 1847



Os 1837

Вес: 2,9

Вставки: Кр 1,4-9; Кр 1,3-2

Os 1840

Вес: 3,9

Вставки: Кр 2,0-12; Кр 1,5-4;

Кр 1,2-2

Os 1845

Вес: 3,5

Вставки: Кр 2,0-8; Кр 1,5-26

Os 1847

Вес: 1,9

Вставки: Кр 2,0-12; Кр 1,5-9

Os 1855

Вес: 6,8

Вставки: Шар 4,2-2; Кр 1,7-20;

Кр 1,4-10



Os 1855



Os 1857



Os1857

Вес: 10,2

Вставки: Шар 8,2-1; Кр 1,8-42;

Кр 1,6-10



Os 1860



Os 1860

Вес: 6,5

Вставки: Кр 1,2-3; Кр 1,1-4



Os 1865



Os 1865

Вес: 2,1

Вставки: Кр 1,2-2; Кр 1,1-4



Os 1867



Os 1870



Os 1875



Os 1877



Os 1867

Вес: 1,7

Вставки: Кр 1,2-3; Кр 1,1-4

Os 1870

Вес: 3,4

Вставки: Кр 1,2-2; Кр 1,1-4

Os 1875

Вес: 2,1

Вставки: Кр 1,2-4; Кр 1,1-4

Os 1877

Вес: 1

Вставки: Кр 1,2-2; Кр 1,1-4

Os 1880

Вес: 5,7

Вставки: Кр 2,5-1; Кр 2,2-1; Кр 2,0-1; Кр 1,8-1; Кр 1,7-1

Os 1885

Вес: 3,5

Вставки: Кр 2,1-2; Кр 2,0-2; Кр 1,8-2; Кр 1,7-2; Кр 1,6-2

Os 1887

Вес: 1,9

Вставки: Кр 2,5-1; Кр 2,1-1; Кр 2,0-1; Кр 1,8-1; Кр 1,7-1; Кр 1,6-1



Os 1880



Os 1885



Os 1887





Os 2143



Os 2144



Os 2145



Os 2146



Os 2143  
Вес: 3,2  
Вставки: Кр 1,0-24

Os 2144  
Вес: 2,4  
Вставки: Кр 1,1-24

Os 2145  
Вес: 1,9  
Вставки: Кр 1,5-37

Os 2146  
Вес: 3,5  
Вставки: Кр 1,5-40



Os 2147




Os 2148



Os 2149



Os 2150



Os 2147  
Вес: 4.3  
Вставки: Кр 1,5-80

Os 2148  
Вес: 3.4  
Вставки: Кв 2,25x2,25-28

Os 2149  
Вес: 3.6  
Вставки: Кв 2,0x2,0-31

Os 2150  
Вес: 11.9



Os 2151



Os 2152



Os 2151


Вес: 6,3

Вставки: Гр 4,0x2,0-1; Кр 0,9-12

Os 2152

Вес: 3,53

Вставки: Кр 3,0-22



Os 2153



Os 2153

Вес: 6.3



Os 2154



Os 2154

Вес: 4



Os 2155



Os 2156



Os 2155  
Вес: 5.7  
Вставки: Кр 1,4-84

Os 2156  
Вес: 8.1  
Вставки: Кр 1,4-14; Кр 1,5-14;  
Кр 1,6-14; Кр 1,7-15



Os 2157



Os 2157  
Вес: 10.8  
Вставки: Кв 2,5x2,5-7;  
Кр 1,4-60



Os 2158



Os 2158  
Вес: 5.9  
Вставки: Баг 3,0x2,0-8; кр-1,2-56



Os 2159



Os 2160



Os 2159

Вес: 8

Вставки: Кр 1,4-45

Os 2160

Вес: 9.5

Вставки: Кр 1,5-6; Кр 1,2-72



Os 2161



Os 2161

Вес: 4.6

Вставки: Кр 3,8-5



Os 2162



Os 2162

Вес: 3.9

Вставки: Кр 2,5-4; Кр 1,2-16



Os 2163



Os 2163  
Вес: 3.4  
Вставки: Кр 1,6-9



Os 2164



Os 2164  
Вес: 3.2  
Вставки: Кр 3,2-1; Кр 2,6-2



Os 2165



Os 2165  
Вес: 1,5  
Вставки: Кр 1,5-16



Os 2166



Os 2166  
Вес: 2.7  
Вставки: Кр 1,1-24



Os 2167



Os 2168



Os 2167  
Вес: 2.7  
Вставки: Кр 2,0-12



Os 2169



Os 2168  
Вес: 4  
Вставки: Кр 4,2-1; Кр 3,4-2



Os 2170



Os 2169  
Вес: 3,1  
Вставки: Кр 1,0-34

Os 2170  
Вес: 4.4  
Вставки: Кр 2,7-6



Os 2171



Os 2171

Вес: 3,2

Вставки: Кр 1,2-24; кр 1,1-46



Os 2172



Os 2172

Вес: 2,9

Вставки: Кр 3,5-1; Кр 2,5-4



Os 2173



Os 2173

Вес: 3,5

Вставки: Кр 1,1-15



Os 2174



Os 2174

Вес: 4,4

Вставки: Кр 3,2-3; Кв 1,5x1,5-4



Os 2175



Os 2176



Os 2177



Os 2178



Os 2175

Вес: 3.9

Вставки: Кр 1,7-12

Os 2176

Вес: 2.7

Вставки: Кр 1,5-16

Os 2177

Вес: 2.7

Вставки: Кр 2,2-11

Os 2178

Вес: 4

Вставки: Кр 3,8-5



Os 2179



Os 2180



Os 2179

Вес: 3.1

Вставки: Кр 1,7-29

Os 2180

Вес: 4.7

Вставки: Кр 3,7-1; кр 3,0-2; кр 1,1-14



Os 2181



Os 2181

Вес: 4.8

Вставки: Кв 2,5x2,5-10



Os 2182



Os 2182

Вес: 4.4

Вставки: Кв 2,0x2,0-10



Os 2183



Os 2184



Os 2183  
Вес: 7  
Вставки: Кр 1,4-48



Os 2185



Os 2184  
Вес: 5  
Вставки: Кр 3,7-5



Os 2186



Os 2185  
Вес: 5.4  
Вставки: Кр 3,3-5

Os 2186  
Вес: 5.9  
Вставки: Кр 3,7-5



Os 2187



Os 2187  
Вес: 4.7  
Вставки: Кр 3,7-5



Os 2188



Os 2188  
Вес: 5.3  
Вставки: Кр 2,7-9



Os 2189



Os 2189  
Вес: 5.3  
Вставки: Кр 1,6-62



Os 2190



Os 2190  
Вес: 2.3  
Вставки: Кр 1,1-27



Os 2191



Os 2192



Os 2191  
Вес: 3.5  
Вставки: Кр 1,3-42



Os 2193



Os 2192  
Вес: 3.5  
Вставки: Кр 1,5-20



Os 2194




Os 2193  
Вес: 4  
Вставки: Кр 1,1-46; кр 1,2-23

Os 2194  
Вес: 5  
Вставки: Кр 2,5-11

Os 2195  
Вес: 3,2  
Вставки: Кр 1,1-26



Os 2195



Os 2196  
Вес: 4,4  
Вставки: Кр 1,0-100



Os 2196



Os 2197  
Вес: 2,4  
Вставки: Кр 1,2-22



Os 2197



Os 2198  
Вес: 3,2  
Вставки: Кр 1,3-34



Os 2198





Os 2199



Os 2200



Os 2199

Вес: 4

Вставки: Кр 1,75-12

Os 2200

Вес: 4

Вставки: Кр 1,2-19



Os 2201



Os 2201

Вес: 3,8

Вставки: Кр 1,2-21



Os 2202



Os 2202

Вес: 6,8

Вставки: Кр 2,0-24



Os 2559



Os 2559  
Вес: 5,8  
Вставки: Кр 5,7-1; кр 1,1-34



Os 2560



Os 2560  
Вес: 3,1  
Вставки: Кр 5,1-1; кр 2,0-14



Os 2561



Os 2561  
Вес: 4  
Вставки: Кр 5,7-1; кр 1,2-40; кр 1,1-16



Os 2562



Os 2562  
Вес: 6,8  
Вставки: Кр 5,7-1; кр 1,0-67



Os 2563



Os 2564



Os 2565



Os 2566



Os 2563

Вес: 5.4

Вставки: Кв 4,5x4,5-1; кр 1-40

Os 2564

Вес: 3.4

Вставки: Кр 5,1-1; кр 1,1-22; кр 1,3-16

Os 2565

Вес: 4

Вставки: Кр 5,7-1; кр 1,0-32; кр 1,1-44

Os 2566

Вес: 3.2

Вставки: Кв 5x5-1; кр 1,1-20; кр 1,0-10

Os 2567

Вес: 4

Вставки: Рв 5,0x5,0-1; кр 1,1-20; кр 1,0-36

Os 2568

Вес: 4.6

Вставки: Кр 5,0-1; кр 1,0-44; кр 1,2-8; кр 3,1-2

Os 2569

Вес: 4.3

Вставки: Кр 6,5-1; кр 2,4-4

Os 2570

Вес: 3.8

Вставки: Кр 6,5-1; кр 3,0-6



Os 2567



Os 2568



Os 2569



Os 2570





Os 2571



Os 2572



Os 2573



Os 2574



Os 2571

Вес: 3.7

Вставки: Кр 6,5-1; кр 2,7-4

Os 2572

Вес: 4

Вставки: Кр 6,5-1; кр 3,8-4

Os 2573

Вес: 4.6

Вставки: Кр 6,5-1; кр 3,0-2; кв 1,5x1,5-4

Os 2574

Вес: 4

Вставки: кр 6,5-1; кр 1,1-44; кр 1,2-68

Os 2575

Вес: 4,2

Вставки: Кр 3,7-1; кр 3,0-2; кр 1,1-14



Os 2575



Os 2576

Вес: 4

Вставки: Кр 6,1-1; кр 2,7-4



Os 2576



Os 2577

Вес: 4

Вставки: Кр 6,1-1; кр 2,7-4



Os 2577



Os 2577

Вес: 5,1

Вставки: Кр 6,5-1; кр 1,75-10



Os 2578



Os 2578

Вес: 3,4

Вставки: Кр 4,0-1; кр 3,0-2; кр 2,7-2



Os 2579



Os 2580



Os 2579

Вес: 8.5

Вставки: Кр 6,5-1; кр 1,1-116

Os 2580

Вес: 3.4

Вставки: Кр 6,5-1; кр 1,5-16



Os 2581



Os 2581

Вес: 5.4

Вставки: Кр 2,2-6



Os 2582



Os 2582

Вес: 2,7

Вставки: Кр 2,5-4; кр 1,2-16

Os 2583

Вес: 4,7

Вставки: Кр 6,5-1; кр 1,3-16; кр 3,0-2



Os 2583



Os 2584

Вес: 3,4

Вставки: Баг 4,0x2,0-3



Os 2584



Os 2585

Вес: 6,8

Вставки: Кр 6,5-1; кр 1,4-36



Os 2585



Os 2586

Вес: 3,4

Вставки: Кр 2,0-3



Os 2586





Os 2587



Os 2588



Os 2589



Os 2590



Os 2587

Вес: 4.9

Вставки: Кв 5,5x5,5-1; кв  
2,0x2,0-8

Os 2588

Вес: 5.4

Вставки: Кр 6,5-1; кр 1,0-4; кр  
1,1-4; кр 1,2-4; кр 1,3-28

Os 2589

Вес: 1.6

Вставки: Мз 4x2-9; Кр 1,5-3

Os 2590

Вес: 3.4

Вставки: Мз 5x2,5-6; Мз 6x3-3;  
Кр 1,75-3

Os 2591

Вес: 2.8

Вставки: Кр 1,6-1; кр 1,3-2; кр 1,0-8; кр 0,9-2



Os 2591



Os 2592

Вес: 5.8

Вставки: Кр 6,0-1; кр 4,0-2; кр 2,0-18



Os 2592



Os 2593

Вес: 4.4

Вставки: Кр 6,0-1; кр 4,0-2; кр 2,0-18



Os 2593



Os 2594

Вес: 4.6

Вставки: Кр 2,4-1; кр 1,5-8; кр 1,2-24; кр 1,1-34



Os 2594





Os 2595



Os 2596



Os 2597



Os 2598



Os 2595

Вес: 2.8

Вставки: Кр 7,0-1; кр 1,2-24

Os 2596

Вес: 6.1

Вставки: ов 8,5х6,5-1; кр 1,5-20;  
кр 1,0-52

Os 2597

Вес: 5.9

Вставки: Кр 5,5-1; кр 1,6-26; кр  
1,4-20; кр 1,2-38

Os 2598

Вес: 5.7

Вставки: Кр 6,5-1; кр 1,6-44; кр  
1,5-18



Os 2599



Os 2599

Вес: 8.2

Вставки: Кв 5,0x5,0-1; кр 1,5-52; кр 1,4-46



Os 2600



Os 2600

Вес: 4

Вставки: кр 6,5-1



Os 2601



Os 2601

Вес: 5.7

Вставки: Кр 6,5-1; кр 1,6-30; кр 1,5-10



Os 2602




Os 2602

Вес: 5.2

Вставки: Кр 5,5-1; кр 2,0-16; 1,7-16



Os 2603



Os 2604



Os 2605



Os 2606



Os 2603

Вес: 5.5

Вставки: Кр 6,5-1; кр 1,6-14;  
кр 1,3-2; кр 1,2-26; кр 1,1-4; кр  
1,0-4

Os 2604

Вес: 4.7

Вставки: Кв 6,0x6,0-1; кр 1,0-36

Os 2605

Вес: 4.3

Вставки: Ов 7,0x5,0-1; кр 1,0-34

Os 2606

Вес: 4.6

Вставки: Сдц 5,9x5,9-1; кр 1,0-  
34



Os 2607



Os 2607

Вес: 6.7

Вставки: Кр 7,5-1; кр 1,5-40; кр 1,4-14; кр 1,3-16; кр 1,2-54



Os 2608



Os 2608

Вес: 4.4

Вставки: Кр 6,5-1; кр 1,7-8; кр 1,5-14; кр 1,4-12; кр 1,3-24



Os 2609



Os 2609

Вес: 5.1

Вставки: Кр 4,8-1; кр 1,5-44; кр 1,1-26



Os 2610



Os 2610

Вес: 6.4

Вставки: Кр 4,3-1; кр 2,0-2; кр 1,7-2; кр 1,5-18; кр 1,4-2; кр 1,1-1



Os 2611



Os 2612



Os 2611

Вес: 3,4

Вставки: Кр 3,2-1; кр 2,6-4

Os 2612

Вес: 6,8

Вставки: Кв 5,0x5,0-1; кр 1,2-84



Os 2613




Os 2613

Вес: 2.7

Вставки: Кр 2,5-1; кр 2,0-2



Os 2614



Os 2614

Вес: 4

Вставки: Кр 1,1-2



Os 2615



Os 2615

Вес: 8.7

Вставки: Кр 4,8-1; бг 2,5x1,5-6,  
кр 1,8-6; кр 1,6-6



Os 2616



Os 2616

Вес: 3.5

Вставки: Кр 2,5-1; кр 2,0-2



Os 2617



Os 2617

Вес: 4.4

Вставки: Кр 6-1; баг 3,5x2,5-2;  
кр 1,7-24 кр 1,6-4; кр 1,1-22



Os 2618



Os 2618

Вес: 4.4

Вставки: Кр 9,1x5,3-1; кр 1,5-1;  
кр 1,3-6; кр 1,2-4; кр 1,1-2; кр  
0,9-8



Os 2619



Os 2620



Os 2619

Вес: 5.4

Вставки: Кр 8,2-1; кр 1,1-34; кр 1,0-16



Os 2621



Os 2620

Вес: 2.4

Вставки: Кр 1,7-7; кр 1,5-5; кр 1,3-2; кр 1,2-6



Os 2622



Os 2621

Вес: 5

Вставки: Кр 10,0-1; кр 1,0-32

Os 2622

Вес: 4.7

Вставки: Кр 5,2-1; кр 3,8-2; кр 1,5-2; кр 1,3-8; кр 1,0-8



Os 2623



Os 2623

Вес: 10,8

Вставки: Кв 5,5x5,5-1; кр 1,2-61; кр 1,1-54



Os 2624



Os 2624

Вес: 4,7

Вставки: Кр 6,0-1; кр 1,3-26; кр 1,0-28



Os 2625



Os 2625

Вес: 3,1

Вставки: Кр 3,7-3



Os 2626



Os 2626

Вес: 3,4

Вставки: Кр 3,7-1; кр 3,6-2



Os 2627



Os 2628



Os 2629



Os 2630



Os 2627

Вес: 3.2

Вставки: Ов 7,5x5,2-1; кр 1,7-2

Os 2628

Вес: 2.9

Вставки: Кр 3,7-1; кр 3,5-2

Os 2629

Вес: 3.5

Вставки: Кр 6,0-1; кр 3,0-2; кр 1,7-6

Os 2630

Вес: 6.2

Вставки: кр 4,0-1; кр 0,9-12

Os 2631

Вес: 6.2

Вставки: кр 4,0-1; кр 0,9-12



Os 2631



Os 2632

Вес: 2.5

Вставки: Ов 5,3х4,1-1; кр 1,9-2



Os 2632



Os 2633

Вес: 4.2

Вставки: Кр 2,8-1; Кр 1,9-2



Os 2633



Os 2634


Вес: 4.6

Вставки: Кр 2,6-1; кр 1,8-2



Os 2634





Os 2635



Os 2636



Os 2635

Вес: 3.4

Вставки: Кр 2,6-1; кр 1,8-2; кр 1,7-2; кр 1,5-2



Os 2637



Os 2636

Вес: 4.8

Вставки: Кр 6,2-1; кр 5,0-2; кр 1,7-2; кр 1,2-2; кр 1,5-6



Os 2638



Os 2637

Вес: 3.7

Вставки: Кр 6,5-1; кр 5,5-2

Os 2638

Вес: 10,2

Вставки: Кв 5,5x5,5-1; кр 1,2-64; кр 1,3-20

Os 2639

Вес: 5.9

Вставки: Кр 7,3-1; кр 4,7-2



Os 2639



Os 2640

Вес: 2.9

Вставки: Гр 8,3x5,1-1



Os 2640



Os 2641

Вес: 5.8

Вставки: Кр 6,5-1; кр 3,5-2; кр 1,5-2



Os 2641



Os 2642

Вес: 5.5

Вставки: Кр 6,0-1; кр 3,3-2; кр 2,3-2; кр 2,0-2; кр 1,8-4; кр 1,5-2



Os 2642





Os 2643



Os 2644



Os 2643

Вес: 6.8

Вставки: Кр 5,5-1; кр 3,1-6; кр 2,6-5; кр 2,5-4; кр 1,6-2; кр 1,3-2



Os 2645



Os 2644

Вес: 4.4

Вставки: Кр 5,1-1

Os 2645

Вес: 3.1

Вставки: Ов 4х6-1



Os 2646



Os 2646

Вес: 2.8

Вставки: Сдц 4,9х5,5-1

Os 2647  
Вес: 2.8  
Вставки: Гр 9,2x5,2-1

Os 2648  
Вес: 3.2  
Вставки: кр 5,6-1

Os 2649  
Вес: 3.1  
Вставки: Баг 7x5-1

Os 2650  
Вес: 3.4  
Вставки: Кр 4,5-1; кр 1,5-10



Os 2647



Os 2648



Os 2649



Os 2650





Os 2651



Os 2652



Os 2653



Os 2654



Os 2651

Вес: 3.1

Вставки: Кр 6,5-1; кр 3,2-2; кр 1,4-28

Os 2652

Вес: 5.4

Вставки: Кр 6,5-1; кр 4,5-2; кр 1,0-14

Os 2653

Вес: 4.2

Вставки: Кр 6,5-1; кр 1,1-62

Os 2654

Вес: 10,8

Вставки: Кр 5,7-1; кр 1,2-18; кр 1,1-98

Os 2655

Вес: 5,7

Вставки: Кр 6,5-1; кр 2,5-2; кр 2,1-2; кр 1,8-2; кр 1,6-4; кр 1,4-2; кр 1,3-52

Os 2656

Вес: 4,9

Вставки: Кр 6,5-1; кр 2,0-26; кр 1,5-30

Os 2657

Вес: 9,5

Вставки: кр 6,5-1; кр 1,1-85

Os 2658

Вес: 5,1

Вставки: Баг 7,0x5,0-1; кр 2,0-8



Os 2655



Os 2656



Os 2657



Os 2658





Os 2659



Os 2660



Os 2659

Вес: 5

Вставки: Кв 6x6-1; кв 2,0-8

Os 2660

Вес: 13,4

Вставки: Кр 5,7-1; кр 1,1-52; кр 1,0-67



Os 2661



Os 2661

Вес: 4

Вставки: Кр 6,5-1; кр 2,0-8



Os 2662



Os 2662

Вес: 4,8

Вставки: Кр 6,2-1; кр 2,5-6

Os 2663

Вес: 5.4

Вставки: Кр 6,8-1; кр 2,0-8



Os 2663



Os 2664

Вес: 3.5

Вставки: Кр 5-1; кр 1,7-8; кр 4,0-2



Os 2664



Os 2665

Вес: 5.8

Вставки: Кр 6,5-1; кр 2,2-6; кр 4,5-2



Os 2665



Os 2666

Вес: 8.1

Вставки: Кр 6,5-1; кр 2,4-10



Os 2666





Os 2667



Os 2668



Os 2667

Вес: 3,4

Вставки: Кр 6,5-1; кр 2,5-2; кр 1,2-16



Os 2669



Os 2668

Вес: 4

Вставки: Кр 6,5-1; баг 4,0x2,0-2



Os 2670



Os 2669

Вес: 3,8

Вставки: Кр 6,0-1; Кр 2,0-2

Os 2670

Вес: 8,7

Вставки: Кр 6,0-1; кр 3,8-9

Os 2671

Вес: 5.5

Вставки: Кр 6,0-1; кр 3,0-13



Os 2671



Os 2672

Вес: 8.1

Вставки: Кр 6,5-1; кр 1,1-112



Os 2672



Os 2673

Вес: 3.8

Вставки: Кр 6,5-1; кр 2,6-4



Os 2673



Os 2674

Вес: 8.9

Вставки: Кр 6,5-1; кр 3,4-4; кр 4,2-1



Os 2674





Os 2675



Os 2676



Os 2675

Вес: 3,6

Вставки: Кр 3,0-1; кр 2,0-2; кр 1,0-4

Os 2676

Вес: 3,2

Вставки: Кр 3,0-1; кр 2,0-2



Os 2677



Os 2677

Вес: 6,3

Вставки: Кр 6,5-1; кр 1,1-39



Os 2678



Os 2678

Вес: 8,1

Вставки: кр 6,5-1; кр 2,0-11

Os 2679

Вес: 6,8

Вставки: кр 6,5-1; кр 3,0-2; кр 2,7-2

Os 2680

Вес: 8,1

Вставки: Кр 6,5-1; кр 1,4-70

Os 2681

Вес: 7,2

Вставки: Кр 6,5-1; кр 1,7-22

Os 2682

Вес: 7

Вставки: Кр 6,5-1; кр 1,1-69



Os 2679



Os2680



Os 2681



Os 2682





Os 2683



Os 2684



Os 2683

Вес: 5,7

Вставки: Кр 6,0-1; кр 1,5-34



Os 2685



Os 2684

Вес: 9,1

Вставки: кр 6,5-1; кр 1,7-20



Os 2686



Os 2685

Вес: 5,1

Вставки: Кр 5,0-1; кр 3,0-2; кр 1,1-16

Os 2686

Вес: 3

Вставки: Кр 2.0-1; кр 1,5-2



Os 2687



Os 2687  
Вес: 6,5  
Вставки: Кр 6,5-1; кр 2,2-4



Os 2688



Os 2688  
Вес: 8,5  
Вставки: Кр 6,5-1; кр 1,4-36



Os 2689



Os 2689  
Вес: 10,2  
Вставки: Кр 6,5-1; кр 2,5-18



Os 2690



Os 2690  
Вес: 4,7  
Вставки: Кр 6,5-1; кр 1,75-10



Os 2691



Os 2692



Os 2693



Os 2694



Os 2691  
Вес: 8,3  
Вставки: Кр 1,2-61

Os 2692  
Вес: 8,1  
Вставки: Кв 5,5x5,5-1; кр 1,3-20; кр 1,2-41

Os 2693  
Вес: 9,1  
Вставки: Кр 6,5-1; кр 1,2-59; кр 1,1-78

Os 2694  
Вес: 9,8  
Вставки: Кр 6,5-1; кр 1,0-94

Os 2695

Вес: 5,4

Вставки: Кр 8,0-1; кр 2,0-27



Os 2695



Os 2696

Вес: 7,3

Вставки: Кр 6,5-1; кр 1,3-18; кр 1,1-49



Os 2696



Os 2697

Вес: 10,2

Вставки: Кр 1,5-48; кр 1,3-4; кр 1,0-4



Os 2697



Os 2698

Вес: 5

Вставки: Кр 6,5-1; Кр 2,0-10



Os 2698





Os 2699



Os 2700



Os 2699

Вес: 6,8

Вставки: Кр 6,5-1; кр 1,1-121

Os 2700

Вес: 6,25

Вставки: Кв 5,5x5,5-1; кр 2,5-10



Os 2701



Os 2701

Вес: 8,9

Вставки: Кр 8,08-1; кр 2,5-2; кр 2,0-8; кр 1,8-4; кр 1,5-4



Os 2702



Os 2702

Вес: 8,1

Вставки: Кр 6,5-1; кр 1,0-85

Os 2703

Вес: 4,3

Вставки: Кр 6,5-1; кр 1,0-38



Os 2703



Os 2704

Вес: 3,9

Вставки: Кр 6,0-1; кр 3,0-20



Os 2704



Os 2705

Вес: 4,8

Вставки: Баг 2,0x0,9-24; кр 2,5-1; кр 2,0-2; кр 1,8-4



Os 2705



Os 2706

Вес: 4,3

Вставки: Кр 6,5-1; кр 3,4-2



Os 2706





Os 2707



Os 2708



Os 2707

Вес: 4,4

Вставки: Кр 6,5-1; кр 3,2-2



Os 2709



Os 2708

Вес: 5,1

Вставки: Ов 7,0x5,0-1; кр 5,0-2

Os 2709

Вес: 4,4

Вставки: Кр 5,5-1; кр 3,7-2



Os 2710



Os 2710

Вес: 4,7

Вставки: Кв 5,5x5,5-1; кв 3,5x3,5-1

Os 2711  
Вес: 4,6  
Вставки: Кр 6,0-1; кр 3,7-2

Os 2712  
Вес: 5,4  
Вставки: Кр 6,0-1; кр 4,5-2

Os 2713  
Вес: 6,1  
Вставки: Баг 7,0x5,0-1; баг 5,0x3,0-2

Os 2714  
Вес: 2,8  
Вставки: Кр 7,0-1; кр 4,5-2



Os 2711



Os 2712



Os 2713



Os 2714





Os 2715



Os 2716



Os 2715

Вес: 5,7

Вставки: Кр 6,2-1; кр 1,5-51

Os 2716

Вес: 5

Вставки: Кр 6,7-1; кр 4,7-2



Os 2717



Os 2717

Вес: 5,3

Вставки: Кр 6,5-1



Os 2718



Os 2718

Вес: 3,8

Вставки: Кр 6,5-1

Os 2719  
Вес: 3,6  
Вставки: Кр 6,5-1



Os 2719



Os 2720  
Вес: 5  
Вставки: Ов 7,0x5,0-1



Os 2720



Os 2721  
Вес: 4  
Вставки: Баг 7,0x5,0-1



Os 2721



Os 2722  
Вес: 3,5  
Вставки: Кр 6,5-1



Os 2722





Os 2723



Os 2724



Os 2723

Вес: 4,4

Вставки: Кр 6,5-1; кр 1,5-4

Os 2724

Вес: 7,2

Вставки: Кв 5,5x5,5-1; кр 1,3-80



Os 2725



Os 2725

Вес: 10,8

Вставки: Кр 3,5-2; кр 4,0-2; кр 3,0-2; кр 2,8-2; кр 2,5-2; кр 2,0-10; кр 1,8-46



Os 2726



Os 2726

Вес: 3,1

Вставки: Кр 3,0-1; кр 2,0-2



Os 3056



Os 3056

Вес: 8.2

Вставки: Кв 3,75x3,75-1; кр 1,5-8




Os 3057





Os 3057

Вес: 8.1

Вставки: Кр 3,2-1



Os 3058



Os 3058

Вес: 9.8

Вставки: Баг 5x4-1; кр 1,3-16



Os 3059



Os 3059

Вес: 6

Вставки: Кр 2,6-4



Os 3060



Os 3061



Os 3060  
Вес: 7.8  
Вставки: Кр 2,3-16



Os 3062



Os 3061  
Вес: 7.2  
Вставки: Кр 1,7-20

Os 3062  
Вес: 7.7  
Вставки: Кр 2,0-16




Os 3063



Os 3063  
Вес: 6.4  
Вставки: Кр 1,7-20



Os 3064



Os 3064

Вес: 8.1

Вставки: Кр 1,8-22; кр 1,5-4



Os 3065



Os 3065

Вес: 7.4

Вставки: Кр 1,6-23; кр 1,5-4; кр 1,3-1; кр 1,2-2



Os 3066



Os 3066

Вес: 5.5

Вставки: Кв 9,7x9,7-1; кр 1,5-8; кр 1,2-8



Os 3067



Os 3067

Вес: 4.3

Вставки: Кр 8,5-1; кр 1,5-12; кр 1,3-12; кр 1,2-14



Os 3068




Os 3069



Os 3068  
Вес: 4.7  
Вставки: Кр 7,1-1



Os 3070



Os 3069  
Вес: 7.4  
Вставки: Кр 3,0-1; Кр 1,0-34



Os 3071



Os 3070  
Вес: 7.6  
Вставки: Кв 2,0x2,0-8

Os 3071  
Вес: 6.2  
Вставки: Ов 14,4 x 12,4-1; кр 2,1-4; кр 1,0-44; кр 0,8-24


Os 3072

Вес: 11.8

Вставки: Кр 2,0-6; кр 1,8-18



Os 3072



Os 3073

Вес: 6.5

Вставки: Кр 0,9-5



Os 3073



Os 3074

Вес: 6.5

Вставки: Кр 0,9-5



Os 3074



Os 3074

Вес: 10.6

Вставки: Кр 12,8-1; кр 1,2-35

Os 3075

Вес: 9.5

Вставки: Кв 21,6 x 21,6-1



Os 3075






Os 3076



Os 3077



Os 3076

Вес: 5.5

Вставки: Кв 7,0x7,0-1; кр 1,7-8;  
кр 1,1-16; кр 1,0-24



Os 3078



Os 3077

Вес: 7.4

Os 3078

Вес: 5.5

Вставки: Ов 6,0x8,0-1; кр 1,3-4;  
кр 1,2-18; кр 1,1-4; кр 1,0-4



Os 3079




Os 3079

Вес: 9.5

Вставки: Кр 5,1-1



Os 3080



Os 3080  
Вес: 8.9  
Вставки: Ов 12,4х10,3-1



Os 3081



Os 3081  
Вес: 10.2  
Вставки:




Os 3082



Os 3082  
Вес: 8.8  
Вставки: Кр 2,3-6




Os 3083




Os 3083  
Вес: 9.5  
Вставки: Кр 1,7-15



Os 3084



Os 3085



Os 3084

Вес: 13

Вставки: Кв 9,0x9,0-1; кр 1,7-8

Os 3085

Вес: 14,6

Вставки: Фантазия  
17,0x5,0x1,5-1; Кр 1,0-20



Os 4041

Os 4041  
 Вес: 1,6  
 Вставки: Кр 4,0-2



Os 4042

Os 4042  
 Вес: 3  
 Вставки: Гр 8,0x5,0-2; гр 5,0x3,0-2; кр 1,5-44



Os 4043

Os 4043  
 Вес: 5  
 Вставки: Гр 6,0x3,0-2; гр 4,0x2,0-2; мз 6,0x2,5-4; мз 4,0x2,0-4; кр 2,5-2; кр 2,3-10; кр 2,0-2; кр 1,8-4; кр 1,5-10



Os 4044

Os 4044  
 Вес: 6,8  
 Вставки: Мз 7,5x4,5-2



Os 4045



Os 4046



Os 4045

Вес: 7,6

Вставки: Кр 2,0-30

Os 4046

Вес: 6,8

Вставки: Кр 1,6-54



Os 4047



Os 4047

Вес: 1,9

Вставки: Кр 2,5-6



Os 4048



Os 4048

Вес: 4

Вставки: Кр 2,1-2; кр 1,6-4; кр 1,2-52



Os 4049



Os 4049

Вес: 2,7

Вставки: Кр 1,6-30; кр 1,1-12;  
кр 1,0-2



Os 4050



Os 4050

Вес: 3

Вставки: Кр 1,2-52



Os 4051




Os 4051

Вес: 3,4

Вставки: Кр 1,2-16; кр 0,9-14



Os 4052



Os 4052

Вес: 4,5


Вставки: Кр 1,2-10; кр 0,9-20;  
кр 0,8-8



Os 4053



Os 4054



Os 4053

Вес: 8,7

Вставки: Шар 12,4-2

Os 4054

Вес: 3

Вставки: Сдц 5,8x5,8-2; кр 1,1-40



Os 4055



Os 4055

Вес: 2,7

Вставки: Кр 1,0-114



Os 4056



Os 4056

Вес: 6,8

Вставки: Кр 1,1-174

Os 4057

Вес: 6,8

Вставки: Кр 2,9-6; кр 1,5-28

Os 4058

Вес: 4,3

Вставки: Кр 1,0-22

Os 4059

Вес: 4

Вставки: Кр 7,0-2; кр 1,1-24; кр 0,8-66

Os 4060

Вес: 5,4

Вставки: Кр 6,5-2; кр 1,3-14; кр 0,8-208



Os 4057



Os 4058



Os 4059



Os 4060






Os 4061



Os 4062



Os 4063



Os 4064



Os 4061

Вес: 5,4

Вставки: Гр 9,0x6,0-2; Кр 1,1-4;

Кр 0,9-18; Кр 0,8-4

Os 4062

Вес: 4

Вставки: Кр 3,5-2

Os 4063

Вес: 5,7

Вставки: Кр 5,0-2

Os 4064

Вес: 4

Вставки: Ов 8x6-2; кр 1,8-28;

кр 1,7-28


Os 4065

Вес: 1,5

Вставки: Ов 6x4-2; кр 1,0-38



Os 4065



Os 4066

Вес: 5,4

Вставки: Ов 10,0x8,0-2; кр 1,5-46



Os 4066



Os 4067

Вес: 5,9

Вставки: Гр 15,0x9,0-2; кр 2,0-12; кр 1,9-2; кр 1,8-14



Os 4067





Os 4068

Вес: 2,4

Вставки: Мз 11,0x5,0-2; кр 1,0-12



Os 4068





Os 4069



Os 4070



Os 4069

Вес: 3,2

Вставки: Бэг 8,0х6,0-2; кр 1,0-34

Os 4070

Вес: 3,5

Вставки: Ов 7,0х5,0-2; кр 1,8-4; 1,5-24



Os 4071



Os 4071

Вес: 9,5

Вставки: Кр 1,7-60; кр 0,9-208




Os 4072



Os 4072

Вес: 3,2

Вставки: Кр 2,5-20



Os 4073

Os 4073

Вес: 3,5

Вставки: Шар 8,0-2; кр 2,1-2



Os 4074

Os 4074

Вес: 4

Вставки: мз 4,0x2,0-12; кр 4,1-2; 1,3-48



Os 4075

Os 4075

Вес: 6,5

Вставки: Кр 3,0-2



Os 4076



Os 4076

Вес: 8



Вставки: Кр 2,5-2; кр 1,8-44; кр 1,5-16; кр 1,0-2



Os 4077



Os 4078



Os 4079



Os 4080



Os 4077

Вес: 6,8

Вставки: Блг 12,0x10,0-2; кр 4,1-2; кр 2,0-42

Os 4078

Вес: 6,2

Вставки: Ов 7,0x5,0-2; кр 0,8-144

Os 4079

Вес: 4

Вставки: Блг 6,0x4,0-2; Кр 1,5-6; Кр 1,2-6; Кр 1,0-52

Os 4080

Вес: 3,5

Вставки: Кр 1,2-4; кр 1,0-2; кр 0,9-82

Os 4081  
Вес: 2,1  
Вставки: Кр 4.0-2




Os 4081



Os 4082  
Вес: 4  
Вставки: Кр 5,0-2



Os 4082



Os 4083  
Вес: 1,6  
Вставки: Кр 1,9-2; кр 1,3-4



Os 4083



Os 4084  
Вес: 1  
Вставки: Кр 2,3-2; кр 1,9-2; кр 1,7-2



Os 4084





Os 4085



Os 4086



Os 4085

Вес: 2,7

Вставки: Кр 1,7-2; кр 1,4-6; кр 1,3-4



Os 4087



Os 4086


Вес: 2,4

Вставки: Кр 1,2-16

Os 4087

Вес: 1,7

Вставки: Шар 8,0-2; кр 2,0-14



Os 4088



Os 4088

Вес: 1,53

Вставки: Кр 1,5-2



Os 4089



Os 4089

Вес: 4,3

Вставки: Кр 1,5-2; Кр 1,0-100



Os 5147



Os 5147

Вес: 3,9

Вставки: Шар 9,9-1; кр 1,4-64;  
кр 1,2-14; кр 1,1-14; кр 1,0-14



Os 5148




Os 5148

Вес: 3,2

Вставки: Шар 11,0-1; кр 1,4-64;  
кр 1,2-14; кр 1,1-14; кр 1,0-14



Os 5149




Os 5149

Вес: 1,5

Вставки: Шар 12x12-1; кр 2,2-2;  
кр 2,0-2; кр 1,7-1; кр 1,6-1; кр  
1,5-3; кр 1,4-3; кр 1,3-1



Os 7127



Os 7128



Os 7127

Вес: 4,3

Вставки: Баг 7,3x5,8-1; баг 4,0x2,5-2; баг 4,0x2,0-4

Os 7128

Вес: 4

Вставки: Баг 6,5x4,0-1; баг 4,5x2,0-4



Os 7129



Os 7129

Вес: 6,1

Вставки: Кр 10,3-1; баг 6,5x2,0-4



Os 7130



Os 7130

Вес: 7,3

Вставки: кр 3,0-1; кр 1,3-24

Os 7131  
Вес: 5,7  
Вставки: Кр 6,0-1



Os 7131



Os 7132  
Вес: 3,4  
Вставки: Гр 9,0x5,9-1; баг 5,0x2,0-4



Os 7132



Os 7133  
Вес: 5  
Вставки: Ов 8,4x6,3-1; кр 1,1-4; кр 1,0-1



Os 7133



Os 7134  
Вес: 5,5  
Вставки: Фантазия 14,6x6,8-1; кр 1,5-26



Os 7134





Os 7135



Os 7136



Os 7137



Os 7138



Os 7135

Вес: 6,4

Вставки: Фантазия 16,5x7,8-1;  
кр 1,6-28

Os 7136

Вес: 2,9

Вставки: Кв 6,2x6,2-1; кр 2,5-1;  
кр 2,0 -2; кр 1,5-2

Os 7137

Вес: 2,7

Вставки: Кр 6,2-1; кр 2,5-2; кр  
2,0 -2; кр 1,5 -2

Os 7138

Вес: 4

Вставки: Баг 8,3x6,3-1; кр 2,3-  
14; кр 1,0-12



Os 7139



Os 7139

Вес: 2,9

Вставки: Гр 9,2x6,2-1; кр 1,1-6



Os 7140



Os 7140

Вес: 5,8

Вставки: Гр 14,7x9,4-1; кр 1,5-27



Os 7141



Os 7141

Вес: 6,8

Вставки: Ов 14,8x10,6-1; кр 1,5-23




Os 7142



Os 7142

Вес: 6,1


Вставки: Кр 14,6-1; кр 1,1-6; кр 1,0-16



Os 7143



Os7144



Os 7143

Вес: 6,5

Вставки: Ов 14,8x12,3-1



Os 7145



Os 7144

Вес: 3,4

Вставки: Ов 13,4x9,8-1



Os 7146



Os 7145

Вес: 5

Вставки: Баг 11,5x9,4-1; мз 4,0x2,0-4

Os 7146

Вес: 4

Вставки: Мз 12,5x6,3-1; кр 1,5-6; кр 1,0-4



Os 7147



Os 7147

Вес: 7

Вставки: Ов 7,0x4,0-1; кр 2,0-15; кр 1,5-13



Os 7148



Os 7148

Вес: 4

Вставки: Ов 11,2x8,4-1; кр 1,0-2




Os 7149



Os 7149

Вес: 10,8

Вставки: Ов 18,5x13,2-1; кр 1,5-34



Os 7150



Os 7150

Вес: 3


Вставки: Ов 8,4x6,4-1; кр 1,0-2



Os 7151



Os 7152



Os 7153



Os 7154



Os 7151

Вес: 2,7

Вставки: Баг 7,2x5,2-1; кр 1,0-2

Os 7152

Вес: 2,5

Вставки: Баг 7,2x5,2-1; кр 1,0-4

Os 7153

Вес: 5,7

Вставки: Кв 12,4x12,4-1

Os 7154

Вес: 6,5

Вставки: Гр 8x5-1; кр 1,9-37; кр 1,2-23



Os 7155



Os 7155

Вес: 2,3

Вставки: Шар 7,2-1; кр 1,2-20



Os 7156



Os 7156

Вес: 5,8

Вставки: Кр 7,2-1; кр 1,9-18; кр 1,6-18; кр 1,3-24



Os 7157



Os 7157

Вес: 5,9

Вставки: Трл 7x7x7-1; кр 1,9-15; кр 1,3-26



Os 7158



Os 7158

Вес: 5,4

Вставки: Кр 5,2-1; кр 1,0-10



Os 7159



Os 7160



Os 7159

Вес: 6,2

Вставки: Ов 6,0х4,0-1; кр 1,0-22

Os 7160

Вес: 8,4

Вставки: Ов 8,0х6,0-1; кр 1,9-4;  
кр 1,8-72; кр 1,3-20; кр 1,2-44;  
кр 1,1-16; кр 1,0-24



Os 7161



Os 7161

Вес: 9,2

Вставки: Кр 3-1; кр 2,8-2; кр  
2,7-9; кр 2,5-5; кр 2,3-6; кр 2,2-  
8; кр 2,0-7; кр 2,01; кр 1,9-2; кр  
1,8-4; кр 1,7-4



Os 7162



Os 7162

Вес: 4,6

Вставки: Кр 8,4-1; кр 1,4-24; кр  
1,3-16; кр 1,2-24; кр 1,0-36



Os 7163



Os 7163

Вес: 3,4

Вставки: Кр 1,0-39; кр 0,9-10



Os 7164



Os 7164

Вес: 4,3

Вставки: Ов 7,0x5,0-1; кр 1,5-8;  
кр 1,0-32



Os 7165



Os 7165

Вес: 4,7

Вставки: Сдц 14,0x14,0-11; кр  
2,0-9; кр 1,9-5



Os 7166



Os 7166

Вес: 13,6

Вставки: Кр 4,2-1; кр 3,8-2; кр  
3,4-1; кр 3,2-2; кр 3,0-6; кр 2,8-  
2; кр 2,7-1; кр 2,5-2; кр 2,4-3; кр  
2,0-2; кр 1,6-4



Os 7167



Os 7168



Os 7167

Вес: 4,4

Вставки: Гр 15,9x10,8-1; кр 1,0-13

Os 7168

Вес: 3

Вставки: Ов 5,2x3,2-1; кр 2,1-2




Os 7169



Os 7169

Вес: 17,2

Вставки: Ов 25,4x18,7-1



Os 7170



Os 7170

Вес: 11,5

Вставки: Кр 16,7-1

Os 7171  
Вес: 12,1  
Вставки: Кв 25,0x25,0-1; кр  
1,6-4





Os 7171



Os 7172  
Вес: 12,5  
Вставки: Баг 27,7x10-1; баг  
23,3x9,4-2



Os 7172



Os 7173  
Вес: 8,9  
Вставки: Кр 26,7-1



Os 7173




Os 7174  
Вес: 3,9  
Вставки: Шар 6,0-1; кр 1,8-1



Os 7174





Os 7175



Os 7176



Os 7175  
Вес: 11,5  
Вставки: Бир 21,6x17,1-1



Os 7177



Os 7176  
Вес: 9,5  
Вставки: Кр 18,7-1




Os 7178



Os 7177  
Вес: 8,1  
Вставки: Гр 20,9x13,5-1

Os 7178  
Вес: 11,9  
Вставки: Кв 19,9x19,9-1



Os 7179



Os 7179  
Вес: 10,5  
Вставки: Кр 20,6-1



Os 7180



Os 7180  
Вес: 8,6  
Вставки: Тр 7,5x7,5-1; кр 2,1-1;  
кр 1,9-17; кр 1,8-8; кр 1,3-25; кр  
1,2-5



Os 7181



Os 7181  
Вес: 8,1  
Вставки: Ов 10x8-1; кр 2,0-22;  
кр 1,1-2; кр 1,3-38; кр 1,2-14



Os 7182



Os 7182  
Вес: 6,1  
Вставки: Кр 4,0-1; кр 1,2-16



Os 7183



Os 7184



Os 7183

Вес: 4,7

Вставки: Кр 3,3-1; кр 1,1-88



Os 7185



Os 7184

Вес: 5,4

Вставки: Кв 9,0x9,0-1; кр 1,0-32



Os 7186



Os 7185

Вес: 3,2

Вставки: Ов 12,9x9,0-1; кр 1,2-30

Os 7186

Вес: 4,9

Вставки: Гр 11,2x5,5-1; кр 5,0-2; кр 1,0-12

Os 7187

Вес: 5,1

Вставки: Кв 8,0x8,0-1; кр 1,3-68



Os 7187



Os 7188

Вес: 4,1

Вставки: Гр 7,4x5,5-1; кр 1,0-55



Os 7188



Os 7189

Вес: 4,1

Вставки: Гр 7,4x5,5-1; кр 1,0-55



Os 7189



Os 7190

Вес: 3,4

Вставки: Кр 4,5-1; кр 1,3-9; кр 1,0-33



Os 7190





Os 7191



Os 7192



Os 7191

Вес: 7,7

Вставки: Кв 9,3x9,3-1; кр 2,4-8

Os 7192

Вес: 5,1

Вставки: Кр 6,5-1; кр 1,3-12; кр 1,0-45



Os 7193



Os 7193

Вес: 4,7

Вставки: Шар 8,0-1; кр 0,9-36



Os 7194



Os 7194

Вес: 4,9

Вставки: Кр 3,5-1; кр 1,3-5; кр 1,0-12



Os 7195



Os 7195

Вес: 3,4

Вставки: Шар 9,7-1; кр 1,0-12;  
кр 0,9-12



Os 7196



Os 7196

Вес: 5,5

Вставки: Ов 9,3x7,3-1; кр 1,0-18




Os 7197



Os 7197

Вес: 5,4

Вставки: сдц 8,4x8,2-1; кр 1,1-19



Os 7198



Os 7198

Вес: 7,2

Вставки: Тр 7,0x6,5-1; кр 2,0-6;  
кр 1,4-6; кр 1,2-3



Os 7199



Os 7200



Os 7201



Os 7202



Os 7199

Вес: 3,9

Вставки: Ов 9,5x7,3-1; кр 1,0-6

Os 7200

Вес: 5,4

Вставки: Мз 10,4x5,3-1; кр 1,2-6

Os 7201


Вес: 5,1

Вставки: Ов 9,5x7,4-1; кр 1,2-10; кр 1,0-22


Os 7202

Вес: 9,9

Вставки: Кр 8,4-1; кр 2,1-6; кр 1,3-2



Os 7203



Os 7204



Os 7203

Вес: 4,6

Вставки: Шар 10,9-1

Os 7204

Вес: 3,8

Вставки: Баг 9,4x7,4-1; кр 1,2-8



Os 7205



Os 7205

Вес: 4,9

Вставки: Шар 7,0-1; кр 1,5-3



Os 7206



Os 7206

Вес: 5,5

Вставки: Ов 11,5x9,4-1; кр 1,7-6; кр 1,3-2



Os 7207



Os 7208



Os 7207

Вес: 3,4

Вставки: Ов 6,1 x 4,2-1; гр 5,7 x 3,0-2; кр 1,3-6

Os 7208

Вес: 3,4

Вставки: Ов 5,1x3,1-1; ов 4,0x3,0-2; кр 1,0-2



Os 7209



Os 7209

Вес: 10,6

Вставки: фантазия 18,5x15,6-1; кр 2,4-6; кр 1,3-4



Os 7210



Os 7210

Вес: 3,2

Вставки: Ов 8,4x6,4-1; кр 1,0-18

Os 7211  
Вес: 11,6  
Вставки: Ов 32,2x21,9-1



Os 7211



Os 7212  
Вес: 4,9  
Вставки: Ов 12,4x8,2-1; ов  
8,5x6,5-2



Os 7212




Os 7213  
Вес: 5  
Вставки: Баг 13,5x10,5-1; кр  
1,1-8



Os 7213




Os 7214  
Вес: 7,4  
Вставки: Баг 16,1x12,5-1; кр  
1,7-2; кр 1,5-18




Os 7214





Os 7215



Os 7216



Os 7217



Os 7218



Os 7215

Вес: 4,3

Вставки: Баг 6,0x5,0-1; трл 4,5-2

Os 7216

Вес: 3,4

Вставки: Шар 6,7-1; кр 2,0-2

Os 7217

Вес: 3,5


Вставки: Гр 4,7x6,9-1; кр 2,5-2

Os 7218

Вес: 4

Вставки: Ов 8x6,6-1

Os 7219  
Вес: 4,3  
Вставки: Ов 11,0x8,0-1



Os 7219



Os 7220  
Вес: 6,8  
Вставки: Ов 8,0x6,0-1; ов  
7,0x5,0-2



Os 7220



Os 7221  
Вес: 6,8  
Вставки: Трл 12,5x12,5x12,5-1



Os 7221



Os 7222  
Вес: 4,7  
Вставки: Шар 8,0-1; кр 1,1-2



Os 7222





Os 7223



Os 7224



Os 7223

Вес: 4,2

Вставки: Шар 7,5-1; кр 1,4-2

Os 7224

Вес: 2,3

Вставки: Мз 6,2x3,2-4; кр 1,3-3




Os 7225



Os 7225

Вес: 6,5

Вставки: Гр 8,0 x 12,0-1; кр 1,0-79



Os 7226




Os 7226

Вес: 2,7


Вставки: Шар 8,5-1; гр 5,0x3,0-2; гр 4,0x2,0-2; кр 1,1-2



Os 7227



Os 7228



Os 7227

Вес: 7

Вставки: Кв 14,0x14,0-1

Os 7228

Вес: 7,3

Вставки: Баг 12x10-1; кр 1,5-36



Os 7229



Os 7229

Вес: 5,1

Вставки: Кр 8,0-1; кр 1,0-8



# Фурнитура

Os 6000 p-p: 14mm вес: 1,2	Os 6001 p-p: 15 mm вес: 1,2	Os 6002 p-p: 15mm вес: 1,5	Os 6003 p-p: 18 mm вес: 1,5	Os 6004 p-p: 15mm вес: 1,1	Os 6005 p-p: 14mm вес: 1,3	Os 6006 p-p: 15 mm вес: 1,1	Os 6007 p-p: 13mm вес: 1,2
Os 6008 p-p: 11mm вес: 1,1	Os 6009 p-p: 11mm вес: 1,5	Os 6010 p-p: d 10mm, кр 2,0-2 вес: 1,7	Os 6011 p-p: 8mm вес: 2,1	Os 6012 p-p: d 10mm вес: 2,1	Os 6013 p-p: d 9 mm, кр 1,5-16 вес: 1,6	Os 6014 p-p: d 11 mm, кр 1,5-16 вес: 1,3	Os 6015 p-p: вес:
Бар. 1 вес: 0,8	Бар. 2 вес: 0,8	Бар. 3 вес: 0,54	Бар. 4 вес: 0,8	Бар. 5 вес: 0,7	Бар. 6 вес: 0,6	Бар. 7 вес: 0,5	Бар. 8 вес: 0,4
Os 6100 вес: 0,4	Os 6101 вес: 0,27	Os 6102 вес: 0,4	Вч 003 вес: 0,1	Вч 005 p-p: 4,5mm вес: 0,6	Вч 035 p-p: 5mm вес: 0,5	Вч 036 p-p: 7mm вес: 0,8	Вч 037 p-p: 8mm вес: 2
Os 6200 p-p: кр 1,5 вес: 0,2	Os 6201 p-p: кр 3,5 вес: 0,13	Os 6202 p-p: кр 4,0 вес: 0,4	Os 6203 p-p: кр 5,0 вес: 0,81	Os 6204 p-p: кр 5,5 вес: 0,95	Os 6205 p-p: кр 6,0 вес: 1,1	Os 6206 p-p: кр 4,0 вес: 0,13	Os 6207 p-p: кр 4,5 вес: 0,2
Os 6008 p-p: кр 5,0 вес: 0,3	Os 6209 p-p: кр 5,5 вес: 0,4	Os 6210 p-p: кр 6,0 вес: 0,81	Os 6211 p-p: кр 7,5 вес: 1,08	Os 6212 p-p: кр 3,0 вес: 0,13	Os 6213 p-p: кр 4,0 вес: 0,32	Os 6214 p-p: кр 5,0 вес: 0,54	Os 6215 p-p: кр 5,5 вес: 0,68
Os 6216 p-p: кр 6,0 вес: 1,08	Os 6217 p-p: кр 2,0 вес: 0,18	Os 6218 p-p: кр 2,5 вес: 0,31	Os 6219 p-p: кр 4,0 вес: 0,4	Os 6220 p-p: кр 3,0 вес: 0,27	Os 6221 p-p: кр 3,6 вес: 0,22	Os 6222 p-p: кр 5,5 вес: 0,42	Os 6223 p-p: кр 2,2 вес: 0,68
Os 6224 p-p: кр 2,5 вес: 0,88	Os 6225 p-p: кр 6,0 вес: 0,5	Os 6226 p-p: кр 5,5 вес: 0,55	Os 6227 p-p: кр 7,0 вес: 0,68	Os 6228 p-p: кр 7,25 вес: 0,27	Os 6229 p-p: кр 5,5 вес: 0,51	Os 6230 p-p: кр 6,5 вес: 0,54	Os 6231 p-p: кр 6,0 вес: 0,81
Os 6232 p-p: кр 5,0 вес: 0,88	Os 6233 p-p: кр 5,0 вес: 0,8	Os 6234 p-p: кр 7,0 вес: 1	Os 6235 p-p: кр 3,0 вес: 0,68	Os 6236 p-p: кр 3,6 вес: 0,95	Os 6237 p-p: кр 5,0 вес: 0,55	Os 6238 p-p: кр 4,8 вес: 0,68	Os 6239 p-p: кр 2,75-1; кр 0,8-8 вес: 0,5
Os 6240 p-p: кр 4,0-1; кр 1,0-9 вес: 0,55	Os 6241 p-p: кр 5,5 вес: 0,41	Os 6242 p-p: кр 4,5-1; кр 0,8-16 вес: 0,41	Os 6243 p-p: кр 5,5-1; кр 3,5-2 вес: 0,81	Os 6244 p-p: ов 8,5x6,5-1 вес: 0,4	Os 6245 p-p: кр 2,0 вес: 0,1	Os 6246 p-p: гр 10,0x6,0-1 вес: 0,8	Os 6247 p-p: кв 5,5x5,5-1 вес: 0,95
Os 6248 p-p: кв 6,3x6,3-1 вес: 1,1	Os 6249 p-p: кв 8,0x8,0-1 вес: 0,96	Os 6250 p-p: кр 2,0 вес: 0,2	Os 6251 p-p: Слц 3,7x3,5-1 вес: 0,5	Os 6252 p-p: Слц 8,0x8,0-1 вес: 0,88	Os 6253 p-p: кр 8,0 вес: 0,95	Os 6254 p-p: кр 6,5 вес: 0,92	Os 6255 p-p: кр 3,0-2 вес: 0,67

Os 6256  
p-p: p: 7,0x5,0-1  
вс: 0,24

Os 6257  
p-p: кр 3,4  
вс: 0,29

Os 6258  
p-p: кр 6,5-1;  
кр 2,0-2  
вс: 0,55

Os 6259  
p-p: кр 5,5  
вс: 0,4

Os 6260  
p-p: кр 7,0  
вс: 0,81

Os 6261  
p-p: кр 8,0  
вс: 0,68

Os 6262  
p-p: кр 5,0  
вс: 0,64

Os 6263  
p-p: кр 2,0-12  
вс: 0,68

Os 6264  
p-p: кр 6,5-1; кр  
4,0-2  
вс: 1,36

Os 6265  
p-p: кр 4,0  
вс: 0,41

Os 6266  
p-p: кр 4,0  
вс: 0,68

Os 6267  
p-p: кр 4,0  
вс: 0,55

Os 6268  
p-p: кр 4,0  
вс: 0,64

Os 6269  
p-p: кр 2,0  
вс: 0,27

Os 6270  
p-p: кр 4,0  
вс: 0,95

Os 6271  
p-p: кр 3,0  
вс: 0,27

Os 6272  
p-p: кр 2,0  
вс: 0,4

Os 6273  
p-p: кр 3,0  
вс: 0,4

Os 6274  
p-p: кр 4,0  
вс: 0,68

Os 6275  
p-p: кр 3,0  
вс: 0,4

Os 6276  
p-p: кв 3,0x3,0  
вс: 0,4

Os 6277  
p-p: кв 4,0x4,0  
вс: 0,54

Os 6278  
p-p: кр 4,0  
вс: 0,4

Os 6279  
p-p: кр 3,0  
вс: 0,27

Os 6280  
p-p: кр 3,0  
вс: 0,4

Os 6281  
p-p: кр 4,0  
вс: 0,4

Os 6282  
p-p: кр 3,0  
вс: 0,55

Os 6284  
p-p: кр 3,0  
вс: 0,4

Os 6285  
p-p: кр 3,5-1;  
кр 3,0-2  
вс:

Os 6286  
p-p: кр 3,0  
вс: 0,4

Os 6287  
p-p: кр 2,0-5  
вс: 1,36

Os 6288  
p-p: кр 4,0  
вс: 0,4

Os 6289  
p-p: кр 3,0  
вс: 0,27

Os 6290  
p-p: кр 3,5-1;  
кр 3,0-2  
вс: 1,08

Вч 001  
p-p: кр 5,0  
вс: 0,15

Вч 004  
p-p: кв 6,0x6,0  
вс: 0,25

Вч 006  
p-p: ов 7,0x5,0  
вс: 0,2

Вч 007  
p-p: кр 2,7  
вс: 0,2

Вч 004  
p-p: кр 2,0  
вс: 0,15

Вч 015  
p-p: кр 2,75  
вс: 0,8

Os 6300  
вс: 0,2

Os 6301  
p-p: кр 1,25-1; кр  
1,1-2; кр 1,0-2  
вс: 0,68

Os 6302  
p-p: кр 1,0-9  
вс: 0,54

Os 6303  
p-p: кр 1,6  
вс: 0,54

Os 6304  
p-p: кр 2,5-1;  
кр 2,0-1  
вс: 0,34

Os 6305  
p-p: кр 1,2-13  
вс: 0,54

Вч 008  
p-p: кр 1,25-1  
вс: 0,3

Вч 009  
вс: 0,25

Вч 017  
p-p: кр 1,25-1  
вс: 0,25

Вч 018  
p-p: кр 1,0-1  
вс: 0,2

Вч 019  
вс: 0,3

Вч 020  
вс: 0,15

Вч 021  
вс: 0,2

Вч 022  
вс: 0,5

Вч 025  
вс: 0,15

Вч 026  
вс: 0,3

1 зам.  
p-p: 8x3 мм  
вс: 0,68

2 зам.  
p-p: 10x3 мм  
вс: 1,2

3 зам.  
p-p: 11,7 x 4,1 мм  
вс: 1,49

4 зам.  
p-p: 13,6 x 5,0 мм  
вс: 1,69

5 зам.  
p-p: 15x6 мм  
вс: 1,76

6 зам.  
p-p: 12,5x7,0 мм  
вс: 1,68

7 зам.  
p-p: 16x5 мм  
вс: 2,17

8 зам.  
вс: 7,1

9 зам.  
p-p: 11x4 мм  
вс: 2,04

10 зам.  
p-p: 20x10 мм  
вс: 6,1

11 зам.  
p-p: 20x10 мм  
вс: 4,4

12 зам.  
p-p: 25x10 мм  
вс: 5,3

13 зам.  
p-p: 13x7 мм  
вс: 1,36

Кор. 1  
p-p: 8,5 мм  
вс: 3,0

Кор. 2  
p-p: 5 мм  
вс: 2,4

Кор. 3  
p-p: 10 мм  
вс: 2,3

Кор. 4  
p-p: 3 мм  
вс: 2,1

Кор. 5  
p-p: кр 2,7-3  
вс: 2

M51130  
p-p: 10 мм  
вс: 7,2

Вч 032  
вс: 3,3

Вч 002  
p-p: d 2 мм  
вс: 0,3

Вч 011  
p-p: d 2 мм  
вс: 0,3

Вч 012  
p-p: d 3,5 мм  
вс: 0,25

Вч 013  
p-p: d 3 мм  
вс: 0,4

Вч 034  
p-p: d 3 мм  
вс: 0,3

Вч 040  
p-p: d 4,5 мм  
вс: 2

Вч 041  
p-p: d 6 мм  
вс: 2,17

Вч 016 p-p:  
18x30 мм  
вс: 3,8

Вч 023  
p-p: 23x25 мм  
вс: 0,12

Вч 024  
p-p: 19x18 мм  
вс: 0,3

Вч 027  
p-p: 17x17 мм  
вс: 0,6

Вч 030  
p-p: 22x18 мм  
вс: 5,1



Вч 033  
р-р: 14 мм  
вес: 1



Шв 001  
р-р: 11 мм  
вес: 0,8



Шв 002  
р-р: 10 мм  
вес: 0,6



Шв 003  
р-р: 13 мм  
вес: 0,9



Шв 004  
р-р: 16 мм  
вес: 0,9



Шв 005  
р-р: 13 мм  
вес: 0,7



Шв 006  
р-р: 2, мм  
вес: 1,1



Шв 007  
р-р: 12 мм  
вес: 0,5



Шв 008  
р-р: 26 мм  
вес: 0,75



Шв 009  
р-р: 10 мм  
вес: 0,6



Шв 010  
р-р: 8 мм  
вес: 0,35



Шв 011  
р-р: 7 мм  
вес: 0,4



Шв 012  
р-р: 10 мм  
вес: 0,5



Вч 028  
р-р: кр 2,0-16  
вес: 2,8



Вч 029  
р-р: 5x14 мм  
вес: 4,6



Вч 031  
р-р: 27x13 мм  
вес: 14,4



